MOTORSPORTS INSPECTION REPORT

MAKE: 2011 Victory VIN: 001886

MODEL: Cross Country ODO: 19354 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
X			IGNITION
X			THROTTLE
			~~TEMPERATURE~~
X			AIR FILTER
X			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
			~~REVERSE GEAR~~
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:

ign good
good throttle response
air filter good
belt good
no fuel leaks
starts / runs
good shift
no leaks

GOOD	OK	FAIL	ELECTRONICS
			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:

lights good
wiring good
switches good
battery good

GOOD	OK	FAIL	BODY / WHEELS & TIRES
X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
			~~BOOT JOINTS~~
X			SUSPENSION
X			FRAME / CHASSIS
	X		PLASTICS / COSMETIC

NOTES:

tires good
bags good
susp good
scratches / ft fender chipped

GOOD	OK	FAIL	BRAKES
X			FRONT BRAKES
X			REAR BRAKES
			~~EMERGENCY BRAKE~~
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:

ft brakes 75% left
rear brakes 70% left
no damages
no leaks

GOOD	OK	FAIL	FLUIDS
X			MOTOR OIL
			~~TRANSMISSION OIL~~
			~~DIFFERENTIAL OIL~~
X			BRAKE FLUIDS
			~~COOLANT / RADIATOR~~

NOTES:

engine oil good
fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED DATE COMPLETED:

INSPECTED BY (SIGNED): SERVICE CONTACT #: (587) 338-8358