MOTORSPORTS INSPECTION REPORT

MAKE: 2019 HD VIN: 501075

MODEL: Street Rod (XL750A) ODO: 740 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
✓			IGNITION
✓			THROTTLE
			~~TEMPERATURE~~
✓			AIR FILTER
✓			DRIVE BELT / CHAIN
✓			FUEL SYSTEM / LINES
✓			SPARK PLUGS
✓			STEERING SYSTEM
✓			EXHAUST SYSTEM
✓			FORWARD GEAR
			~~REVERSE GEAR~~
✓			NEUTRAL / IDLE
✓			SEALS / GASKETS

NOTES:
- ign good
- good throttle movement
- air filter good
- drive good
- no fuel leaks
- starts / runs
- good shift
- no leaks

GOOD	OK	FAIL	ELECTRONICS
✓			HEAD LIGHT
✓			TAIL LIGHT
✓			BRAKE LIGHT
✓			HAZARDS
✓			BATTERY
✓			INSTRUMENT PANEL
✓			WIRING / SWITCHES

NOTES:
- lights good
- wiring good
- switches good
- battery good > tender

GOOD	OK	FAIL	BRAKES
✓			FRONT BRAKES
✓			REAR BRAKES
			~~EMERGENCY BRAKE~~
✓			BRAKE MASTER CYLINDER
✓			BRAKE HOSES / LINES
✓			BRAKE LEVERS

NOTES:
- ft brakes 90% left
- rear brakes 90% left
- no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRES
✓			TIRE WEAR / PSI
✓			LUGS TORQUED
✓			WHEEL BEARINGS
			~~BOOT JOINTS~~
✓			SUSPENSION
✓			FRAME / CHASSIS
	✓		PLASTICS / COSMETIC

NOTES:
- tires good
- bags good
- susp good
- minor scratches (tip)

GOOD	OK	FAIL	FLUIDS
✓			MOTOR OIL
			~~TRANSMISSION OIL~~
			~~DIFFERENTIAL OIL~~
✓			BRAKE FLUIDS
			~~COOLANT / RADIATOR~~

NOTES:
- new engine oil / filter
- fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: March 22/22

INSPECTED BY (SIGNED):

SERVICE CONTACT #: (587) 338-8358