

MOTORSPORTS INSPECTION REPORT

MAKE: 2017 Honda VIN: 100227
 MODEL: CRF 1000 ODO: 12315 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
X			IGNITION
X			THROTTLE
X			TEMPERATURE
			AIR FILTER
X			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:
 ign good
 good throttle response
 drive system good
 no fuel leaks
 starts / runs
 good shift
 no engine leaks

GOOD	OK	FAIL	ELECTRONICS
X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:
 lights good
 wiring / switches good
 battery good

GOOD	OK	FAIL	BRAKES
X			FRONT BRAKES
X			REAR BRAKES
			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:
 ff brakes 90% left
 rear brakes 85% left
 ff brake lever stewed.

GOOD	OK	FAIL	BODY / WHEELS & TIRES
X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
			BOOT JOINTS
X			SUSPENSION
X			FRAME / CHASSIS
	X		PLASTICS / COSMETIC


NOTES:
 tires good
 bearings good
 susp good
 minor scuffing RHS

GOOD	OK	FAIL	FLUIDS
X			MOTOR OIL
			TRANSMISSION OIL
			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

NOTES:
 engine oil clean
 brake fluids good
 coolant level good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Age 11/23

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358