

MOTORSPORTS INSPECTION REPORT

MAKE: 2020 HD VIN: 017728

MODEL: Street Bob ODO: 5534 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

<input checked="" type="checkbox"/>			IGNITION
<input checked="" type="checkbox"/>			THROTTLE
			TEMPERATURE
<input checked="" type="checkbox"/>			AIR FILTER
<input checked="" type="checkbox"/>			DRIVE BELT / CHAIN
<input checked="" type="checkbox"/>			FUEL SYSTEM / LINES
<input checked="" type="checkbox"/>			SPARK PLUGS
<input checked="" type="checkbox"/>			STEERING SYSTEM
<input checked="" type="checkbox"/>			EXHAUST SYSTEM
<input checked="" type="checkbox"/>			FORWARD GEAR
			REVERSE GEAR
<input checked="" type="checkbox"/>			NEUTRAL / IDLE
<input checked="" type="checkbox"/>			SEALS / GASKETS

IGNITION
THROTTLE
TEMPERATURE
AIR FILTER
DRIVE BELT / CHAIN
FUEL SYSTEM / LINES
SPARK PLUGS
STEERING SYSTEM
EXHAUST SYSTEM
FORWARD GEAR
REVERSE GEAR
NEUTRAL / IDLE
SEALS / GASKETS

NOTES:

ign good
throttle response good
cleaned air filter
belt tension good
no fuel leaks
starts & runs
good shift
no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

<input checked="" type="checkbox"/>			HEAD LIGHT
<input checked="" type="checkbox"/>			TAIL LIGHT
<input checked="" type="checkbox"/>			BRAKE LIGHT
<input checked="" type="checkbox"/>			HAZARDS
<input checked="" type="checkbox"/>			BATTERY
<input checked="" type="checkbox"/>			INSTRUMENT PANEL
<input checked="" type="checkbox"/>			WIRING / SWITCHES

HEAD LIGHT
TAIL LIGHT
BRAKE LIGHT
HAZARDS
BATTERY
INSTRUMENT PANEL
WIRING / SWITCHES

NOTES:

lights good
wiring good
battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

<input checked="" type="checkbox"/>			FRONT BRAKES
<input checked="" type="checkbox"/>			REAR BRAKES
			EMERGENCY BRAKE
<input checked="" type="checkbox"/>			BRAKE MASTER CYLINDER
<input checked="" type="checkbox"/>			BRAKE HOSES / LINES
<input checked="" type="checkbox"/>			BRAKE LEVERS

FRONT BRAKES
REAR BRAKES
~~EMERGENCY BRAKE~~
BRAKE MASTER CYLINDER
BRAKE HOSES / LINES
BRAKE LEVERS

NOTES:

ft brakes 95% left
rear brakes 85% left
no damages
no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

<input checked="" type="checkbox"/>			TIRE WEAR / PSI
<input checked="" type="checkbox"/>			LUGS TORQUED
<input checked="" type="checkbox"/>			WHEEL BEARINGS
			BOOT JOINTS
<input checked="" type="checkbox"/>			SUSPENSION
<input checked="" type="checkbox"/>			FRAME / CHASSIS
	<input checked="" type="checkbox"/>		PLASTICS / COSMETIC

TIRE WEAR / PSI
LUGS TORQUED
WHEEL BEARINGS
~~BOOT JOINTS~~
SUSPENSION
FRAME / CHASSIS
PLASTICS / COSMETIC

NOTES:

new ft tire
brgs good
susp good
minor scratches/tank chipped

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

<input checked="" type="checkbox"/>			MOTOR OIL
<input checked="" type="checkbox"/>			TRANSMISSION OIL
			DIFFERENTIAL OIL
<input checked="" type="checkbox"/>			BRAKE FLUIDS
			COOLANT / RADIATOR

MOTOR OIL
TRANSMISSION OIL
~~DIFFERENTIAL OIL~~
BRAKE FLUIDS
~~COOLANT / RADIATOR~~

NOTES:

replaced engine oil/filter
trans oil clean
fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Mar 24/22

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358