

MOTORSPORTS INSPECTION REPORT

MAKE: Ducati VIN: 059124
 MODEL: Monster 696 ODO: 9697 kms -

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

x			IGNITION
x			THROTTLE
x			TEMPERATURE
			AIR FILTER
x			DRIVE BELT / CHAIN
x			FUEL SYSTEM / LINES
x			SPARK PLUGS
x			STEERING SYSTEM
x			EXHAUST SYSTEM
x			FORWARD GEAR
			REVERSE GEAR
x			NEUTRAL / IDLE
x			SEALS / GASKETS

NOTES:

ign good
 good throttle response
 chain & sprocket good
 fuel system good
 starts & runs
 good shift
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

x			HEAD LIGHT
x			TAIL LIGHT
x			BRAKE LIGHT
x			HAZARDS
x			BATTERY
x			INSTRUMENT PANEL
x			WIRING / SWITCHES

NOTES:

lights good
 wiring good
 battery good
 has fender

GOOD	OK	FAIL	BRAKES
------	----	------	--------

x			FRONT BRAKES
x			REAR BRAKES
			EMERGENCY BRAKE
x			BRAKE MASTER CYLINDER
x			BRAKE HOSES / LINES
x			BRAKE LEVERS

NOTES:

ft brakes 75% left
 rear brakes 80% left
 no damages
 no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRE
------	----	------	----------------------

x			TIRE WEAR / PSI
x			LUGS TORQUED
x			WHEEL BEARINGS
			BOOT JOINTS
x			SUSPENSION
x			FRAME / CHASSIS
x			PLASTICS / COSMETIC

NOTES:

tires good
 bags good
 susp good
 very clean unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------


x			MOTOR OIL
			TRANSMISSION OIL
			DIFFERENTIAL OIL
x			BRAKE FLUIDS
x			COOLANT / RADIATOR

NOTES:

engine oil clean
 brake fluids good
 clutch fluid good
 cooler good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Dec 15/22

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358