

# MOTORSPORTS INSPECTION REPORT

MAKE: 2020 BMW VIN: 692525  
 MODEL: R1250 RS ODO: 3634kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			
α			

IGNITION  
 THROTTLE  
 TEMPERATURE  
 AIR FILTER  
 DRIVE BELT / CHAIN  
 FUEL SYSTEM / LINES  
 SPARK PLUGS  
 STEERING SYSTEM  
 EXHAUST SYSTEM  
 FORWARD GEAR  
 REVERSE GEAR  
 NEUTRAL / IDLE  
 SEALS / GASKETS

NOTES:

ign good  
 good throttle play/response  
 ran to temp good  
 air filter good  
 no fuel leaks  
 starts & runs  
 good shift  
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

α			
α			
α			
α			
α			
α			
α			
α			

HEAD LIGHT  
 TAIL LIGHT  
 BRAKE LIGHT  
 HAZARDS  
 BATTERY  
 INSTRUMENT PANEL  
 WIRING / SWITCHES

NOTES:

lights good  
 wiring good  
 switches good  
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

α			
α			
α			
α			
α			
α			

FRONT BRAKES  
 REAR BRAKES  
 EMERGENCY BRAKE  
 BRAKE MASTER CYLINDER  
 BRAKE HOSES / LINES  
 BRAKE LEVERS

NOTES:

ft brakes 95% left  
 rear brakes 95% left  
 no leaks  
 no damage

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

α			
α			
α			
α			
α			
α			
α			
α			

TIRE WEAR / PSI  
 LUGS TORQUED  
 WHEEL BEARINGS  
 BOOT TORNTS  
 SUSPENSION  
 FRAME / CHASSIS  
 PLASTICS / COSMETIC

NOTES:

tires good  
 bolts good  
 suspension good / no leaks  
 clean unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

α			
α			
α			
α			

MOTOR OIL  
 TRANSMISSION OIL  
 DIFFERENTIAL OIL  
 BRAKE FLUIDS  
 COOLANT / RADIATOR

NOTES:

engine oil clean  
 diff oil clean  
 fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: June 26/23

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358