

MOTORSPORTS INSPECTION REPORT

MAKE: 2019 Honda VIN: 0000002

MODEL: CBR500 ODD: 23 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

α		
α		
α		
α		
α		
α		
α		
α		
α		
α		
α		
α		
α		
α		
α		

- IGNITION
- THROTTLE
- TEMPERATURE
- AIR FILTER
- DRIVE BELT / CHAIN
- FUEL SYSTEM / LINES
- SPARK PLUGS
- STEERING SYSTEM
- EXHAUST SYSTEM
- FORWARD GEAR
- REVERSE GEAR
- NEUTRAL / IDLE
- SEALS / GASKETS

NOTES:

ign good
good throttle play
air filter good
chain/sprockets good
no fuel leaks
starts/runs
good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

α		
α		
α		
α		
α		
α		
α		

- HEAD LIGHT
- TAIL LIGHT
- BRAKE LIGHT
- HAZARDS
- BATTERY
- INSTRUMENT PANEL
- WIRING / SWITCHES

NOTES:

lights good
wiring good
battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

α		
α		
α		
α		
α		
α		

- FRONT BRAKES
- REAR BRAKES
- EMERGENCY BRAKE
- BRAKE MASTER CYLINDER
- BRAKE HOSES / LINES
- BRAKE LEVERS

NOTES:

ft brakes 95% left
rear brakes 95% left
no clunks
no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

α		
α		
α		
α		
α		
α		
α		

- TIRE WEAR / PSI
- LUGS TORQUED
- WHEEL BEARINGS
- BOOT JOINTS
- SUSPENSION
- FRAME / CHASSIS
- PLASTICS / COSMETIC

NOTES:

tires good
brgs good
susp good
clean

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

α		
α		
α		
α		

- MOTOR OIL
- TRANSMISSION OIL
- DIFFERENTIAL OIL
- BRAKE FLUIDS
- COOLANT / RADIATOR

NOTES:

engine oil check
fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: July 20/23

INSPECTED BY (SIGNED):

SERVICE CONTACT #: (587) 338-8358