

# MOTORSPORTS INSPECTION REPORT

MAKE: 2003 BMW

VIN: D79803

MODEL: K 1200 LT

ODO: 41962 miles

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

α			IGNITION
α			THROTTLE
α			TEMPERATURE
α			AIR FILTER
			DRIVE BELT / CHAIN
α			FUEL SYSTEM / LINES
α			SPARK PLUGS
α			STEERING SYSTEM
α			EXHAUST SYSTEM
α			FORWARD GEAR
α			<del>REVERSE GEAR</del>
α			NEUTRAL / IDLE
α			SEALS / GASKETS

NOTES:	
ign good	
throttle plug good	
air filter good	
no fuel leaks	
starts & runs	
good shift	

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

α			HEAD LIGHT
α			TAIL LIGHT
α			BRAKE LIGHT
α			HAZARDS
α			BATTERY
α			INSTRUMENT PANEL
α			WIRING / SWITCHES

NOTES:	
lights good	
wiring good	
switches good	
new battery	

GOOD	OK	FAIL	BRAKES
------	----	------	--------

α			FRONT BRAKES
α			REAR BRAKES
			EMERGENCY BRAKE
α			BRAKE MASTER CYLINDER
α			BRAKE HOSES / LINES
α			BRAKE LEVERS

NOTES:	
ft brakes 75% left	
rear brakes 50% left	
no damages	

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

α			TIRE WEAR / PSI
α			LUGS TORQUED
α			WHEEL BEARINGS
			<del>BOOT JOINTS</del>
α			SUSPENSION
α			FRAME / CHASSIS
	α		PLASTICS / COSMETIC

NOTES:	
tires good	
brake good	
susp good	
switches / RHS mirror cracked	


GOOD	OK	FAIL	FLUIDS
------	----	------	--------

α			MOTOR OIL
			<del>TRANSMISSION OIL</del>
			DIFFERENTIAL OIL
α			BRAKE FLUIDS
α			COOLANT / RADIATOR

NOTES:	
oil good	
coolant good	
brake fluids good	

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: May 12/23

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358