

# MOTORSPORTS INSPECTION REPORT

MAKE: 2007 Suzuki VIN: 105184  
 MODEL: C50T Boulevard ODO: 32093 km

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

X			IGNITION
X			THROTTLE
X			TEMPERATURE
X			AIR FILTER
X			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
X			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:

ign good  
 good throttle play  
 air filter good  
 no fuel issues  
 starts & runs  
 good shift  
 no issues

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:

lights good  
 wiring good  
 switches good  
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

X			FRONT BRAKES
X			REAR BRAKES
X			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:

ft brakes 85% left  
 rear drum brakes 80% left  
 no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
X			<del>BOOT JOINTS</del>
X			SUSPENSION
X			FRAME / CHASSIS
X			PLASTICS / COSMETIC

NOTES:

tires good  
 bearings good  
 swap good  
 tank minor scratch

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

X			MOTOR OIL
X			<del>TRANSMISSION OIL</del>
X			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

NOTES:

oils good  
 brake fluids good  
 coolant good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: June 10/24

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358