

MOTORSPORTS INSPECTION REPORT

MAKE: 2023 Indian VIN: 009955

MODEL: CHIEF Bobber ODO: 11309 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

☒		
☒		
☒		
☒		
☒		
☒		
☒		
☒		
☒		
☒		
☒		
☒		

IGNITION
THROTTLE
~~TEMPERATURE~~
AIR FILTER
DRIVE BELT / CHAIN
FUEL SYSTEM / LINES
SPARK PLUGS
STEERING SYSTEM
EXHAUST SYSTEM
FORWARD GEAR
~~REVERSE GEAR~~
NEUTRAL / IDLE
SEALS / GASKETS

NOTES:

ign good
throttle play good
air filter ok
drive system good
no fueling issues
starts / runs
good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

☒		
☒		
☒		
☒		
☒		
☒		
☒		

HEAD LIGHT
TAIL LIGHT
BRAKE LIGHT
HAZARDS
BATTERY
INSTRUMENT PANEL
WIRING / SWITCHES

NOTES:

lights good
wiring good
switches good
battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

☒		
☒		
☒		
☒		
☒		

FRONT BRAKES
REAR BRAKES
~~EMERGENCY BRAKE~~
BRAKE MASTER CYLINDER
BRAKE HOSES / LINES
BRAKE LEVERS

NOTES:

ft brakes 80% left
rear brakes 80% left
no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

☒		
☒		
☒		
☒		
☒		
☒		
☒		

TIRE WEAR / PSI
LUGS TORQUED
WHEEL BEARINGS
~~BOOT JOINTS~~
SUSPENSION
FRAME / CHASSIS
PLASTICS / COSMETIC

NOTES:

tires good
bgs good
susp good
chain unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

☒		
☒		
☒		

MOTOR OIL
~~TRANSMISSION OIL~~
DIFFERENTIAL OIL
BRAKE FLUIDS
COOLANT / RADIATOR

NOTES:

oil good
fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED:

Jan 9/25

INSPECTED BY (SIGNED):

SERVICE CONTACT #: (587) 338-8358