

MOTORSPORTS INSPECTION REPORT

MAKE: Victory VIN: 004801
 MODEL: Jackpot ODO: 41133 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

IGNITION
 THROTTLE
~~TEMPERATURE~~
 AIR FILTER
 DRIVE BELT / CHAIN
 FUEL SYSTEM / LINES
 SPARK PLUGS
 STEERING SYSTEM
 EXHAUST SYSTEM
 FORWARD GEAR
~~REVERSE GEAR~~
 NEUTRAL / IDLE
 SEALS / GASKETS

NOTES:
ign good
good throttle play
air filter OK
belt good
fuel system good
starts / runs
good shift
no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

HEAD LIGHT
 TAIL LIGHT
 BRAKE LIGHT
 HAZARDS
 BATTERY
 INSTRUMENT PANEL
 WIRING / SWITCHES

NOTES:
lights good
wiring good
battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

FRONT BRAKES
 REAR BRAKES
~~EMERGENCY BRAKE~~
 BRAKE MASTER CYLINDER
 BRAKE HOSES / LINES
 BRAKE LEVERS

NOTES:
ft brakes 90% left
rear brakes 75% left
no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

TIRE WEAR / PSI
 LUGS TORQUED
 WHEEL BEARINGS
~~BOOT JOINTS~~
 SUSPENSION
 FRAME / CHASSIS
 PLASTICS / COSMETIC

NOTES:
tires good
bgs good
susp good
minor scratches

GOOD	OK	FAIL	FLUIDS
------	----	------	--------


☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

MOTOR OIL
 TRANSMISSION OIL
 DIFFERENTIAL OIL
 BRAKE FLUIDS
 COOLANT / RADIATOR

NOTES:
oil good
brake fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: July 4/25

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358