

MOTORSPORTS INSPECTION REPORT

MAKE: 2017 HD VIN: 604297
 MODEL: Ultra ODO: 46626 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

☒			IGNITION
☒			THROTTLE
			TEMPERATURE
			AIR FILTER
☒			DRIVE BELT / CHAIN
☒			FUEL SYSTEM / LINES
☒			SPARK PLUGS
☒			STEERING SYSTEM
☒			EXHAUST SYSTEM
☒			FORWARD GEAR
☒			REVERSE GEAR
☒			NEUTRAL / IDLE
☒			SEALS / GASKETS

NOTES:

ign good
 good throttle play
 air filter good
 belt good
 no fuel issues
 starts / runs
 good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

☒			HEAD LIGHT
☒			TAIL LIGHT
☒			BRAKE LIGHT
☒			HAZARDS
☒			BATTERY
☒			INSTRUMENT PANEL
☒			WIRING / SWITCHES

NOTES:

lights good
 wiring good
 switches good
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

☒			FRONT BRAKES
☒			REAR BRAKES
			EMERGENCY BRAKE
☒			BRAKE MASTER CYLINDER
☒			BRAKE HOSES / LINES
☒			BRAKE LEVERS

NOTES:

ft brakes 80% left
 rear brakes 75% left
 no leaks
 scuffing on brake lever

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

☒			TIRE WEAR / PSI
☒			LUGS TORQUED
☒			WHEEL BEARINGS
☒			BOOT JOINTS
☒			SUSPENSION
☒			FRAME / CHASSIS
☒			PLASTICS / COSMETIC

NOTES:

new tires ft; rear
 bgs good
 susp good
 clean unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------


☒			MOTOR OIL
☒			TRANSMISSION OIL
			DIFFERENTIAL OIL
☒			BRAKE FLUIDS
			COOLANT / RADIATOR

NOTES:

oils good
 brake fluids good
 no leaks

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Sept 24/24

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358