

SNOWMOBILE INSPECTION REPORT

MAKE: 2017 Arctic Cat VIN: 107632

MODEL: M8000 162 ODO: 694 miles

GOOD	OK	FAIL	ENGINE / MECHANICAL
------	----	------	---------------------

α			COMPRESSION
α			SPARK PLUGS
α			CLUTCH
α			DRIVE BELT
α			FUEL SYSTEM
α			REVERSE GEAR
α			NEUTRAL / IDLE
α			SEALS / GASKETS
α			ENGINE OIL
α			INJECTION OIL
α			COOLANT

NOTES:

comp 120/120 psi ✓
 plugs good
 clutches clean
 belt tension good
 starts/runs
 coolant good
 good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

α			HEADLIGHT
α			TAIL LIGHT
α			BRAKE LIGHT
α			HEATED GRIPS / WARMERS
α			INSTRUMENT PANEL
α			SWITCHES
α			THROTTLE OPERATION

NOTES:

lights good
 switches good
 battery good
 throttle play good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

α			BRAKE LEVER
α			BRAKE PADS
α			BRAKE MASTER CYLINDER

NOTES:

brakes good
 85% left on pads
 no damages

GOOD	OK	FAIL	BODY / PHYSICAL
------	----	------	-----------------

α			HOOD
α			TUNNEL
α			SKI CONDITION
α			SKAGS (RUNNERS)
α			TRACK SLIDERS
α			TRACK DRIVERS
α			SEAT CONDITION

NOTES:

hood good
 tunnel good
 sliders good
 ski & skags good

GOOD	OK	FAIL	SUSPENSION / TRACK
------	----	------	--------------------

α			FRONT SUSP. / STEERING
α			REAR SUSP. / RAILS
α			TRACK / TRACK TENSION

NOTES:

susp good
 rails good
 track good

INSPECTED BY (PRINT): UNLEASHED CYCLE & SLED

DATE COMPLETED: Nov 16/23

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358