

MOTORSPORTS INSPECTION REPORT

MAKE: 2017 Moto Guzzi VIN: 000106
 MODEL: California ODO: 18523 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

X			IGNITION
X			THROTTLE
			TEMPERATURE
			AIR FILTER
			DRIVE BELT / CHAIN
			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
X			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:
 ign switch good
 throttle ply good
 starts/runs
 no fuel leaks
 good shift
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:
 lights good
 wiring good
 switches good
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

X			FRONT BRAKES
	X		REAR BRAKES
			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:
 fr brakes 95% left
 rear brakes 50% left
 no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
			BOOT JOINTS
			SUSPENSION
X			FRAME / CHASSIS
X	X		PLASTICS / COSMETIC

NOTES:
 tires good
 bags good
 susp good
 scratches in black paint

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

X			MOTOR OIL
			TRANSMISSION OIL
			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

NOTES:
 engine oil clean
 diff oil good
 brake fluid good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

INSPECTED BY (SIGNED): 

DATE COMPLETED: Apr 9/24

SERVICE CONTACT #: (587) 338-8358