

MOTORSPORTS INSPECTION REPORT

MAKE: 2014 Suzuki VIN: 101084
 MODEL: Boulevard C50T ODO: 10329 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
X			IGNITION
X			THROTTLE
X			TEMPERATURE
X			AIR FILTER
			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:

ign good
 throttle play good
 air filter ok
 no fuel leaks
 starts & runs
 good shift
 no leaks

GOOD	OK	FAIL	ELECTRONICS
X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:

lights good - repaired fog
 wiring good
 switches good
 battery good - has tender

GOOD	OK	FAIL	BRAKES
X			FRONT BRAKES
X			REAR BRAKES
			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:

ft brakes 90% left
 rear brakes 85% left
 no damages
 no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRES
X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
			BOOT JOINTS
X			SUSPENSION
X			FRAME / CHASSIS
	X		PLASTICS / COSMETIC

NOTES:

tires good
 bearings good
 suspension good
 minor scratches

GOOD	OK	FAIL	FLUIDS
X			MOTOR OIL
			TRANSMISSION OIL
X			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

NOTES:

replaced engine oil/filter
 rear diff oil good
 fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: APRIL 27/22

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358