

MOTORSPORTS INSPECTION REPORT

MAKE: 2018 Moto Guzzi VIN: 000057
 MODEL: V7 ODO: 3417 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
X			IGNITION
X			THROTTLE
X			TEMPERATURE
X			AIR FILTER
			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:
 ign good
 throttle play good
 air filter OK
 starts & runs
 good shift
 no leaks

GOOD	OK	FAIL	ELECTRONICS
X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:
 lights good
 wiring good
 battery good

GOOD	OK	FAIL	BRAKES
X			FRONT BRAKES
X			REAR BRAKES
X			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:
 ft brakes 85% left
 rear brakes 90% left
 no damages
 no leaks

GOOD	OK	FAIL	BODY / WHEELS & TIRES
X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
			BOOT JOINTS
X			SUSPENSION
X			FRAME / CHASSIS
X			PLASTICS / COSMETIC

NOTES:
 tires good
 bolts good
 susp good
 clean unit

GOOD	OK	FAIL	FLUIDS
X			MOTOR OIL
			TRANSMISSION OIL
X			DIFFERENTIAL OIL
X			BRAKE FLUIDS
			COOLANT / RADIATOR

NOTES:
 new oil filter
 diff oil good
 no leaks

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Sept 12/22

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358