

# MOTORSPORTS INSPECTION REPORT

MAKE: 2016 Suzuki VIN: 100407  
 MODEL: Boulevard C50T ODO: 7056 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

x		
x		
x		
x		
x		
x		
x		
x		
x		
x		
x		
x		
x		
x		
x		

IGNITION  
 THROTTLE  
 TEMPERATURE  
 AIR FILTER  
 DRIVE BELT / CHAIN *shaft*  
 FUEL SYSTEM / LINES  
 SPARK PLUGS  
 STEERING SYSTEM  
 EXHAUST SYSTEM  
 FORWARD GEAR  
 REVERSE GEAR  
 NEUTRAL / IDLE  
 SEALS / GASKETS

NOTES:  
 ign good  
 good throttle response  
 air filter clean  
 drive shaft good  
 starts & runs  
 good shift  
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

x		
x		
x		
x		
x		
x		
x		
x		

HEAD LIGHT  
 TAIL LIGHT  
 BRAKE LIGHT  
 HAZARDS  
 BATTERY  
 INSTRUMENT PANEL  
 WIRING / SWITCHES

NOTES:  
 lights good  
 wiring good  
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

x		
x		
x		
x		
x		
x		

FRONT BRAKES  
 REAR BRAKES  
 EMERGENCY BRAKE  
 BRAKE MASTER CYLINDER  
 BRAKE HOSES / LINES  
 BRAKE LEVERS

NOTES:  
 ft brakes 85% left  
 rear brakes 80% left  
 no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

x		
x		
x		
x		
x		
x		
x		
x		

TIRE WEAR / PSI  
 LUGS TORQUED  
 WHEEL BEARINGS  
 BOOT JOINTS  
 SUSPENSION  
 FRAME / CHASSIS  
 PLASTICS / COSMETIC

NOTES:  
 tires good  
 brgs good  
 susp good  
 minor tank scratches

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

x		
x		
x		
x		
x		

MOTOR OIL  
 TRANSMISSION OIL  
 DIFFERENTIAL OIL  
 BRAKE FLUIDS  
 COOLANT / RADIATOR

NOTES:  
 engine oil clean  
 rear diff clean  
 coolant good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Apr 15/22

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358