MOTORSPORTS INSPECTION REPORT

MAKE: 2003 VIN: 700149

MODEL: Honda Shadow ODO: 21316

GOOD	OK	FAIL	ENGINE / TRANSMISSION
✓			IGNITION
✓			THROTTLE
✓			TEMPERATURE
			~~AIR FILTER~~
			~~DRIVE BELT / CHAIN~~
✓			FUEL SYSTEM / LINES
✓			SPARK PLUGS
✓			STEERING SYSTEM
✓			EXHAUST SYSTEM
✓			FORWARD GEAR
			~~REVERSE GEAR~~
✓			NEUTRAL / IDLE
✓			SEALS / GASKETS

NOTES:
ign good
Throttle good
no fuel leaks
starts + runs
good shift
no leaks

GOOD	OK	FAIL	ELECTRONICS
✓			HEAD LIGHT
✓			TAIL LIGHT
✓			BRAKE LIGHT
✓			HAZARDS
✓			BATTERY
✓			INSTRUMENT PANEL
✓			WIRING / SWITCHES

NOTES:
lights good
battery good
wiring good

GOOD	OK	FAIL	BODY / WHEELS & TIRES
✓			TIRE WEAR / PSI
✓			LUGS TORQUED
✓			WHEEL BEARINGS
			~~BOOT JOINTS~~
✓			SUSPENSION
	✓		FRAME / CHASSIS
	✓		PLASTICS / COSMETIC

NOTES:
tires good
bags good
suspension good
minor scratches

GOOD	OK	FAIL	BRAKES
✓			FRONT BRAKES
✓			REAR BRAKES
			~~EMERGENCY BRAKE~~
✓			BRAKE MASTER CYLINDER
✓			BRAKE HOSES / LINES
✓			BRAKE LEVERS

NOTES:
ft brakes 80% left
rear brakes 80% left
no damages

GOOD	OK	FAIL	FLUIDS
✓			MOTOR OIL
			~~TRANSMISSION OIL~~
✓			DIFFERENTIAL OIL
✓			BRAKE FLUIDS
✓			COOLANT / RADIATOR

NOTES:
engine oil clean
diff oil good
brake fluid good
coolant good

INSPECTED BY (PRINT): Unleashed Cycle & Sled
CERTIFIED RED SEAL MECHANIC

DATE COMPLETED: July 16/21

INSPECTED BY (SIGNED):

SERVICE CONTACT #: 587-338-8358