

MOTORSPORTS INSPECTION REPORT

MAKE: 2024 Can Am VIN: 001689
 MODEL: Outlander 700 ODO: 565kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

✓			IGNITION
✓			THROTTLE
✓			TEMPERATURE
✓			AIR FILTER
✓			DRIVE BELT / CHAIN
✓			FUEL SYSTEM / LINES
✓			SPARK PLUGS
✓			STEERING SYSTEM
✓			EXHAUST SYSTEM
✓			FORWARD GEAR
✓			REVERSE GEAR
✓			NEUTRAL / IDLE
✓			SEALS / GASKETS

NOTES:
ign good
good throttle play
air f. filter good
Drive belt good
no fuel issues
starts and runs
good shift
no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

✓			HEAD LIGHT
✓			TAIL LIGHT
✓			BRAKE LIGHT
✓			HAZARDS
✓			BATTERY
✓			INSTRUMENT PANEL
✓			WIRING / SWITCHES

NOTES:
lights good
wiring good
switches good
battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

✓			FRONT BRAKES
✓			REAR BRAKES
✓			EMERGENCY BRAKE
✓			BRAKE MASTER CYLINDER
✓			BRAKE HOSES / LINES
✓			BRAKE LEVERS

NOTES:
ft brakes so do left
rear brakes good left
no damage

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

✓			TIRE WEAR / PSI
✓			LUGS TORQUED
✓			WHEEL BEARINGS
✓			BOOT JOINTS
✓			SUSPENSION
✓			FRAME / CHASSIS
✓			PLASTICS / COSMETIC

NOTES:
tires good
bags good
susp good
minor plastic scratches


GOOD	OK	FAIL	FLUIDS
------	----	------	--------

✓			MOTOR OIL
✓			TRANSMISSION OIL
✓			DIFFERENTIAL OIL
✓			BRAKE FLUIDS
✓			COOLANT / RADIATOR

NOTES:
oil good
coolant good
brake fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Sept 16/25

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358