

# MOTORSPORTS INSPECTION REPORT

MAKE: 2021 HD VIN: 417680  
 MODEL: XL1200 SPORTY 48 ODO: 405 km

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

X			IGNITION
X			THROTTLE
X			TEMPERATURE
X			AIR FILTER
X			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
X			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

**NOTES:**  
 ign good  
 throttle good  
 air filter clean  
 belt good  
 starts & runs  
 good shift  
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

**NOTES:**  
 lights good  
 wiring good  
 battery good / has tender

GOOD	OK	FAIL	BRAKES
------	----	------	--------

X			FRONT BRAKES
X			REAR BRAKES
X			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

**NOTES:**  
 ft brakes 95% left  
 rear brakes 95% left  
 no damage

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
X			BOOT JOINTS
X			SUSPENSION
X			FRAME / CHASSIS
X			PLASTIC / COSMETIC

**NOTES:**  
 tires good  
 bags good  
 susp good  
 clean

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

X			MOTOR OIL
X			TRANSMISSION OIL
X			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

**NOTES:**  
 replaced engine oil / f.l.t.o  
 brake fluids good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Nov 30/22

INSPECTED BY (SIGNER): 

SERVICE CONTACT #: (587) 338-8358