

MOTORSPORTS INSPECTION REPORT

MAKE: 2022 Decati VIN: 008646
 MODEL: Hypermoto 950 ODO: 2348 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

X			IGNITION
X			THROTTLE
X			TEMPERATURE
X			AIR FILTER
X			DRIVE BELT / CHAIN
X			FUEL SYSTEM / LINES
X			SPARK PLUGS
X			STEERING SYSTEM
X			EXHAUST SYSTEM
X			FORWARD GEAR
X			REVERSE GEAR
X			NEUTRAL / IDLE
X			SEALS / GASKETS

NOTES:

ign good
 Throttle good
 air filter good
 chain/sprockets good
 starts/runs
 good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

X			HEAD LIGHT
X			TAIL LIGHT
X			BRAKE LIGHT
X			HAZARDS
X			BATTERY
X			INSTRUMENT PANEL
X			WIRING / SWITCHES

NOTES:

lights good
 wiring good
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

X			FRONT BRAKES
X			REAR BRAKES
X			EMERGENCY BRAKE
X			BRAKE MASTER CYLINDER
X			BRAKE HOSES / LINES
X			BRAKE LEVERS

NOTES:

ff brakes 95% left
 rear brakes 85% left
 no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

X			TIRE WEAR / PSI
X			LUGS TORQUED
X			WHEEL BEARINGS
X			BOOT JOINTS
X			SUSPENSION
X			FRAME / CHASSIS
X			PLASTICS / COSMETIC

NOTES:

tires good
 bbs good
 susp good
 clean unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------


X			MOTOR OIL
X			TRANSMISSION OIL
X			DIFFERENTIAL OIL
X			BRAKE FLUIDS
X			COOLANT / RADIATOR

NOTES:

engine oil clean
 brake fluids
 coolant good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Mar 17/23

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358